



Tenhulzen kept the existing window in the hall bath to draw natural light. Vanity mirrors are suspended by a cable system.

The scope of this remodel required tearing the entire second floor down to the studs. Since the kitchen is just below the master bath, preventing dust from drifting down through the car decking was “a bit of a challenge,” Tenhulzen says. Dust control, safety, and security build the trust with their clients that ensures a lasting relationship and a solid referral source.

To ensure the clients’ comfort during production, Tenhulzen built a ramp up to the scaffolding and created a “construction entrance” in the exterior wall to access the upstairs without traversing the home’s formal entry and other first-floor living areas. Demolition debris was carried out through this entrance; mechanical and electrical components and drywall were brought in the same way. Access through the front door was limited to the final two weeks of the project, which greatly reduced potential damage to the furniture-quality entry porch and narrow, twisting stairwell. **PR**



Sweet Music To Your Ears: “APPROVED.”

If you’re frustrated with credit turndowns from your first-look lender, this powerful financing program will have you whistling a new tune.

Our flexible underwriters will approve many of your credit-challenged customers, with no equity ever required.

Are You Ready To Strike A New Chord?

Contact Jack Maschmeier at
(866) 234-5010 x5560 or
JackM@HomePlusFinance.com



©2014 HomePlus Finance Corp